









# MANDALAY

upholstery fabric

Suggested Applications for this pattern are:

-  Corporate     Church     Healthcare  
 Home Office     Hospitality     Institutional

|   |  |
|---|--|
| Fiber Content:                          | 100% Polyolefin  |
| Width:                                  | 54" (137 / 140cm)  |
| Weight:                                 | 11.0 ± 1 Oz./Linear Yard   |
| Repeat:                                 | 1 <sup>3</sup> / <sub>16</sub> " H 1 <sup>1</sup> / <sub>16</sub> " V  |
| Backing:                                | Acrylic  |
| Abrasion:<br>(Wyzenbeek ASTM-D-4157-02) | 50,000 Double Rubs*  |
| Tensile Strength:<br>(ASTM-D-5034-90)   | W: 50 lbs. F: 50 lbs.  |
| Seam Slippage:<br>(ASTM-D-4034-92)      | W: 84 lbs F: 101 lbs.  |
| Lightfastness:<br>(AATCC-16A-1990)      | 40 Hours, Class 5  |
| Colorfastness:<br>(AATCC-8-1989)        | Wet - Class 4.5<br>Dry - Class 4.5   |
| Crocking:<br>(AATCC-8-1989)             | Wet - Class 4.5<br>Dry - Class 4.5   |
| Flame Resistance:                       | California, Tech Bulletin 117, Section E: 191-53 Class 1<br>UFAC, Class 1<br>BIFMA - Class 1<br>NFPA 260-A, Class 1<br>B.S. 5852 Part 1: 1979 Ignition Source 0; smoldering cigarette<br>Fabrics can be treated to meet these additional fire codes:<br>FMVSS 302<br>Boston Fire Dept. BFD 1X-1<br>New York Port Authority |
| Cleaning Code:                          | W/S - For water based stains use water based cleaning agent, For oil based stains use solvent cleaner.<br>*Testing was stopped at this point. Sample had not failed.   |

## **DPC™ Daniel Paul Chairs** LLC

### Manufacturing Facility and General Office

2052 S. Economy Road  
Morristown, TN 37813  
Phone: 423.586.9977 Fax.: 423.586.9927

Web Site: [danielpaulchairs.com](http://danielpaulchairs.com)

E-mail: [sales@danielpaulchairs.com](mailto:sales@danielpaulchairs.com)